


PLAN



SECTION AT A-A

NOTE:

1. All joints must be solvent welded
2. Dimension of the Redgum support as per design.
3. All bolts to be galvanised
4. Flanged and solvent welded joints applicable